


CNC TURN/ MILL CENTRE

- Up to 7 Axes
- 6 side complete machining
- Manufacturing from bars or blanks material



Watch Parts



Medical



Aerospace



Micromechanics



Jewellery



Horizontal Transfer Milling Machine

- Transfer-machine, 9 working stations, 36 working axes
- Manufacturing from bar
- Productivity and flexibility united




Station 1




Roughing outer form of part

Station 2




Finishing outer form of part

Station 3




Roughing / finishing of front groove

Station 4




Roughing / finishing of precision bore

Station 5




Drill core hole and tap front thread

Station 6




Roughing / finishing upper precision bore

Station 7




Roughing / finishing lateral groove

Station 8




Cut-off part

Station 9



Roughing / finishing 6th side

Station 10



Bar feed